Oil Field Environmental Incident Summary

Responsible Party: denbury

Well Operator: DENBURY ONSHORE, LLC

Well Name: TRMU 14-14H

Field Name: T. R. Well File #: 15834

Date Incident:1/10/2014Time Incident:1400Facility ID Number:County:BILLINGSTwp:141Rng:101Sec:14Qtr:

Location Description:

Submitted By: Mark VanGrinsven Received By:

Contact Person:

5320 LEGACY DR

PLANO, TX 75024-3127

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:2 MilesDistance Nearest Water Well:2 Miles

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

	Spillea	Units	Recoverea	Units
Oil	2	barrels	2	barrels
Brine	3	barrels	3	barrels
Other	0	barrels	0	barrels

Description of Other Released Contaminant:

On the state of the train

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

Followup Units

Potential Environmental Impacts:

none

Action Taken or Planned:

well is shut in and line is isolated. Fluids were recovered via vac truck. Excavation of the line and any contaminated soils will commence after lines have been located

Wastes Disposal Location: contractor will dispose

Agencies Involved:

Updates

Date: 1/13/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, from a piping leak on location, remained on location within the diking, according to the report. NDIC retains oversight.